



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

S232297

D3574-6

Job Sheet 203206



Part No: D3574-6

Job Qty: 2 pcs

Part Name: Cabin Floor Protector



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/13/19

Job Tracking No:

Due Date: 11/29/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG REV B IPP Rev :A New Issue 07.07.23 EC verified by:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Waterjet - Flow - 1	2 pcs	11/29/19	11/29/19	0.17	0.79	Waterjet - Flow		<i>SRB 11/15/19</i>
110	QC 2	2 pcs	11/29/19	11/29/19	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		
							QC 2 - 65		

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 813 632-5200
Email: sales@dartaero.com
www.dartaero.com



Container No: S232297

Part: D3574-6
Job No: 203206
Serial No/Batch: S232297

Revision:
Inspector:
Exp Date:
Instructions: Various STC's

Date: 11/15/19

Plex 11/13/19 8:01 AM Dart.lajeunesse.marie

120 QC 8	2 pcs	11/29/19	0.00 0.00	QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	RRS
				QC 8 - 12	SRB 11/15/19
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	
				QC 8 - 9	
				QC 8 - 68	DAS
				QC 8 - 67	NOV 18 2019 68
				QC 8 - 1 (A)	9-89
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
				QC 8 - 61	
150 Packaging 3-1 - Stock - B4B	2 pcs	11/29/19	0.00 0.00	Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	DAS
				Packaging 3 - 6 - B4B	28
				Packaging 3 - 7 - B4B	9-89
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	

				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
160 QC 21 - SA	2 pcs	11/29/19	0.00 0.00	QC 21 - SA - 21	21
				QC 21 - SA - 70	21
				QC 21 - SA - 53	21
Part Op 100 - 1-Cut as per Dwg D3574 Dwg Rev: _____ Prog Rev: _____ 2-Deburr if necessary Descriptions: 110 - (QC2- Inspect parts off machine FAI/FAIB) 120 - (QC8- Inspect parts - second check) 150 - (Identify as per dwg & Stock Location: _____) 160 - (QC21- Final Inspection - Work Order Release)					
Job BOM					
Part / Item	Component Name	Quantity	Operation	Container	
MLEXS.125-F60029-04	GE Plastics Lexan Sheet (Dark Grey)	48 sf (24 ea)	100-Waterjet - Flow - 1	5165915	
Job Allocations					
Operation	Component Part	Required	Inventory	Allocated	
100-Waterjet - Flow - 1	MLEXS.125-F60029-04	48	1,138	0	
Part Specifications					
Specifications could not be found.					

Plex 11/13/19 8:01 AM Dart.lajeunesse.marie

DART AEROSPACE LTD		Work Order: 203206
Description: Cabin Floor Protector		Part Number: D3574-6
Inspection Dwg: D3574	Rev: B	Page 1 of 2

FIRST ARTICLE INSPECTION CHECKLIST

☒ First Article ☐ Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø3.00	+0.006/-0.001	2.999				
7.37	+/-0.030	7.36				
11.00	+/-0.030	11.00				
15.25	+/-0.030	15.26				
25.87	+/-0.030	25.88				
39.75	+/-0.030	39.75				
44.75	+/-0.030	44.75				
58.38	+/-0.030	58.39				
63.50	+/-0.030	63.55				
65.25	+/-0.030	65.25				
10.25	+/-0.030	10.26				
11.87	+/-0.030	11.85				
14.75	+/-0.030	14.76				
26.00	+/-0.030	26.00				
40.87	+/-0.030	40.86				
45.00	+/-0.030	45.00				
48.00	+/-0.030	48.00				
55.13	+/-0.030	55.15				
61.25	+/-0.030	61.26				
61.88	+/-0.030	61.88				
64.63	+/-0.030	64.65				
1.13	+/-0.030	1.13				
7.63	+/-0.030	7.65				
11.00	+/-0.030	11.00				
22.10	+/-0.030	22.12				
22.50	+/-0.030	22.55				
24.50	+/-0.030	24.52				
35.13	+/-0.030	35.14				
36.50	+/-0.030	36.55				
40.00	+/-0.030	40.00				
41.88	+/-0.030	41.89				
43.63	+/-0.030	43.65				
6.75	+/-0.030	6.76				
9.50	+/-0.030	9.52				

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube ☐ Cross tube ☐ Eng. (Non-AW) ☐ Machining ☐ Small Fab ☐ Prod. Eng. Coord. ☐ Large Fab ☐ Finishing ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐																															
Date :	Sequence #:	QTY Affected :		MRB (QS1042)																															
Description Work Order Deviation		Disposition																																	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>Contamination</td> <td>Power Loss/Surge</td> <td>Positioned Wrong</td> </tr> <tr> <td>Bending</td> <td>Misaligned/off center</td> <td>Folio/Program</td> <td>Outside Tolerance</td> </tr> <tr> <td>Crushing</td> <td>BOM/Route</td> <td>Grain Direction</td> <td>Drawing</td> </tr> <tr> <td>Cracks</td> <td>Broken/Damage/Defect</td> <td>Weld</td> <td>Finish</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>Incomplete/Unclear Instructions</td> <td>Wrong Stock Pulled</td> <td>Part Lost/Missing</td> </tr> <tr> <td>Marks/Chatter</td> <td>Drill Holes</td> <td>Out of Sequence</td> <td>Misread</td> </tr> <tr> <td>Mislabeled</td> <td>Fit/Function</td> <td>Off-set/Set-up</td> <td></td> </tr> </table>						Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	Crushing	BOM/Route	Grain Direction	Drawing	Cracks	Broken/Damage/Defect	Weld	Finish	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	Marks/Chatter	Drill Holes	Out of Sequence	Misread	Mislabeled	Fit/Function	Off-set/Set-up	
		Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong																														
		Bending	Misaligned/off center	Folio/Program	Outside Tolerance																														
Crushing	BOM/Route	Grain Direction	Drawing																																
Cracks	Broken/Damage/Defect	Weld	Finish																																
Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing																																
Marks/Chatter	Drill Holes	Out of Sequence	Misread																																
Mislabeled	Fit/Function	Off-set/Set-up																																	
Other/Details:																																			
		Completed By		Lead hand / Supervisor																															
		QC / QA Coordinator																																	